

American National Standard Z535.2 states "A visual alerting device in the form of a sign, label, decal, placard or other marking which advised the observer of the nature and degree of the potential hazard(s) which can cause an accident. It may also provide other directions to eliminate the hazards and may advise of the probable consequences of not avoiding the hazard"

Materials



*Visually Intensive; Meets Latest ANSI Z535.2*

Safety alert symbol →

International pictogram →

Lettering is left justified to enhance legibility →

Select your size and material for part number-example ..... AN-1723 (7"x10" PL-plastic sign) →

7x10 AL AN-1721 FG AN-1722 PL AN-1723 VPO AN-1724	7x10 AL AN-3121 FG AN-3122 PL AN-3123 VPO AN-3124	7x10 AL AN-1821 FG AN-1822 PL AN-1823 VPO AN-1824	7x10 AL AN-3221 FG AN-3222 PL AN-3223 VPO AN-3224	7x10 AL AN-1921 FG AN-1922 PL AN-1923 VPO AN-1924	7x10 AL AN-2021 FG AN-2022 PL AN-2023 VPO AN-2024
10x14 AL AN-1731 FG AN-1732 PL AN-1733 VPO AN-1734	10x14 AL AN-3131 FG AN-3132 PL AN-3133 VPO AN-3134	10x14 AL AN-1831 FG AN-1832 PL AN-1833 VPO AN-1834	10x14 AL AN-3231 FG AN-3232 PL AN-3233 VPO AN-3234	10x14 AL AN-1931 FG AN-1932 PL AN-1933 VPO AN-1934	10x14 AL AN-2031 FG AN-2032 PL AN-2033 VPO AN-2034

7x10 AL AN-3321 FG AN-3322 PL AN-3323 VPO AN-3324	7x10 AL AN-2121 FG AN-2122 PL AN-2123 VPO AN-2124	7x10 AL AN-2221 FG AN-2222 PL AN-2223 VPO AN-2224	7x10 AL AN-2321 FG AN-2322 PL AN-2323 VPO AN-2324	7x10 AL AN-2421 FG AN-2422 PL AN-2423 VPO AN-2424	7x10 AL AN-3421 FG AN-3422 PL AN-3423 VPO AN-3424	7x10 AL AN-0121 FG AN-0122 PL AN-0123 VPO AN-0124	7x10 AL AN-4521 FG AN-4522 PL AN-4523 VPO AN-4524
10x14 AL AN-3331 FG AN-3332 PL AN-3333 VPO AN-3334	10x14 AL AN-2131 FG AN-2132 PL AN-2133 VPO AN-2134	10x14 AL AN-2231 FG AN-2232 PL AN-2233 VPO AN-2234	10x14 AL AN-2331 FG AN-2332 PL AN-2333 VPO AN-2334	10x14 AL AN-2431 FG AN-2432 PL AN-2433 VPO AN-2434	10x14 AL AN-3431 FG AN-3432 PL AN-3433 VPO AN-3434	10x14 AL AN-0131 FG AN-0132 PL AN-0133 VPO AN-0134	10x14 AL AN-4531 FG AN-4532 PL AN-4533 VPO AN-4534

7x10 AL AN-0221 FG AN-0222 PL AN-0223 VPO AN-0224	7x10 AL AN-0321 FG AN-0322 PL AN-0323 VPO AN-0324	7x10 AL AN-0421 FG AN-0422 PL AN-0423 VPO AN-0424	7x10 AL AN-0521 FG AN-0522 PL AN-0523 VPO AN-0524	7x10 AL AN-3521 FG AN-3522 PL AN-3523 VPO AN-3524	7x10 AL AN-3621 FG AN-3622 PL AN-3623 VPO AN-3624	7x10 AL AN-0621 FG AN-0622 PL AN-0623 VPO AN-0624	7x10 AL AN-0721 FG AN-0722 PL AN-0723 VPO AN-0724
10x14 AL AN-0231 FG AN-0232 PL AN-0233 VPO AN-0234	10x14 AL AN-0331 FG AN-0332 PL AN-0333 VPO AN-0334	10x14 AL AN-0431 FG AN-0432 PL AN-0433 VPO AN-0434	10x14 AL AN-0531 FG AN-0532 PL AN-0533 VPO AN-0534	10x14 AL AN-3531 FG AN-3532 PL AN-3533 VPO AN-3534	10x14 AL AN-3631 FG AN-3632 PL AN-3633 VPO AN-3634	10x14 AL AN-0631 FG AN-0632 PL AN-0633 VPO AN-0634	10x14 AL AN-0731 FG AN-0732 PL AN-0733 VPO AN-0734

7x10 AL AN-0821 FG AN-0822 PL AN-0823 VPO AN-0824	7x10 AL AN-0921 FG AN-0922 PL AN-0923 VPO AN-0924	7x10 AL AN-1021 FG AN-1022 PL AN-1023 VPO AN-1024	7x10 AL AN-1121 FG AN-1122 PL AN-1123 VPO AN-1124	7x10 AL AN-3821 FG AN-3822 PL AN-3823 VPO AN-3824	7x10 AL AN-3921 FG AN-3922 PL AN-3923 VPO AN-3924	7x10 AL AN-4021 FG AN-4022 PL AN-4023 VPO AN-4024	7x10 AL AN-3721 FG AN-3722 PL AN-3723 VPO AN-3724
10x14 AL AN-0831 FG AN-0832 PL AN-0833 VPO AN-0834	10x14 AL AN-0931 FG AN-0932 PL AN-0933 VPO AN-0934	10x14 AL AN-1031 FG AN-1032 PL AN-1033 VPO AN-1034	10x14 AL AN-1131 FG AN-1132 PL AN-1133 VPO AN-1134	10x14 AL AN-3831 FG AN-3832 PL AN-3833 VPO AN-3834	10x14 AL AN-3931 FG AN-3932 PL AN-3933 VPO AN-3934	10x14 AL AN-4031 FG AN-4032 PL AN-4033 VPO AN-4034	10x14 AL AN-3731 FG AN-3732 PL AN-3733 VPO AN-3734

- If You Don't See It, We Can Make It!
- Custom Jobs Our Specialty...Please Call For A Quote!

# American National Standards Institute ANSI Signs


THE SIGNS OF A SAFE INDUSTRY

Visually Intensive; Meets Latest American National Standard Z535.2-1998

Materials



7x10 AL AN-2521  
FG AN-2522  
PL AN-2523  
VPO AN-2524  
10x14 AL AN-2531  
FG AN-2532  
PL AN-2533  
VPO AN-2534



7x10 AL AN-2621  
FG AN-2622  
PL AN-2623  
VPO AN-2624  
10x14 AL AN-2631  
FG AN-2632  
PL AN-2633  
VPO AN-2634



7x10 AL AN-2721  
FG AN-2722  
PL AN-2723  
VPO AN-2724  
10x14 AL AN-2731  
FG AN-2732  
PL AN-2733  
VPO AN-2734



7x10 AL AN-2921  
FG AN-2922  
PL AN-2923  
VPO AN-2924  
10x14 AL AN-2931  
FG AN-2932  
PL AN-2933  
VPO AN-2934



7x10 AL AN-4121  
FG AN-4122  
PL AN-4123  
VPO AN-4124  
10x14 AL AN-4131  
FG AN-4132  
PL AN-4133  
VPO AN-4134



7x10 AL AN-4221  
FG AN-4222  
PL AN-4223  
VPO AN-4224  
10x14 AL AN-4231  
FG AN-4232  
PL AN-4233  
VPO AN-4234




7x10 AL AN-2821  
FG AN-2822  
PL AN-2823  
VPO AN-2824  
10x14 AL AN-2831  
FG AN-2832  
PL AN-2833  
VPO AN-2834



7x10 AL AN-4321  
FG AN-4322  
PL AN-4323  
VPO AN-4324  
10x14 AL AN-4331  
FG AN-4332  
PL AN-4333  
VPO AN-4334



7x10 AL AN-4421  
FG AN-4422  
PL AN-4423  
VPO AN-4424  
10x14 AL AN-4431  
FG AN-4432  
PL AN-4433  
VPO AN-4434



7x10 AL AN-3021  
FG AN-3022  
PL AN-3023  
VPO AN-3024  
10x14 AL AN-3031  
FG AN-3032  
PL AN-3033  
VPO AN-3034




7x10 AL AN-1321  
FG AN-1322  
PL AN-1323  
VPO AN-1324  
10x14 AL AN-1331  
FG AN-1332  
PL AN-1333  
VPO AN-1334



7x10 AL AN-1421  
FG AN-1422  
PL AN-1423  
VPO AN-1424  
10x14 AL AN-1431  
FG AN-1432  
PL AN-1433  
VPO AN-1434




7x10 AL AN-4621  
FG AN-4622  
PL AN-4623  
VPO AN-4624  
10x14 AL AN-4631  
FG AN-4632  
PL AN-4633  
VPO AN-4634



7x10 AL AN-4721  
FG AN-4722  
PL AN-4723  
VPO AN-4724  
10x14 AL AN-4731  
FG AN-4732  
PL AN-4733  
VPO AN-4734



7x10 AL AN-1521  
FG AN-1522  
PL AN-1523  
VPO AN-1524  
10x14 AL AN-1531  
FG AN-1532  
PL AN-1533  
VPO AN-1534



7x10 AL AN-1621  
FG AN-1622  
PL AN-1623  
VPO AN-1624  
10x14 AL AN-1631  
FG AN-1632  
PL AN-1633  
VPO AN-1634

## ANSI Graphic Machine Labels

International machine safety labels are available in three sizes:

1.75" x 2.5" - 2" x 3" - 3" x 5"




1.7x2.5 VPO ML-011  
2x3 VPO ML-012  
3x5 VPO ML-013




1.7x2.5 VPO ML-021  
2x3 VPO ML-022  
3x5 VPO ML-023




1.7x2.5 VPO ML-031  
2x3 VPO ML-032  
3x5 VPO ML-033



1.7x2.5 VPO ML-041  
2x3 VPO ML-042  
3x5 VPO ML-043



1.7x2.5 VPO ML-051  
2x3 VPO ML-052  
3x5 VPO ML-053



1.7x2.5 VPO ML-061  
2x3 VPO ML-062  
3x5 VPO ML-063



1.7x2.5 VPO ML-071  
2x3 VPO ML-072  
3x5 VPO ML-073



1.7x2.5 VPO ML-081  
2x3 VPO ML-082  
3x5 VPO ML-083



1.7x2.5 VPO ML-091  
2x3 VPO ML-092  
3x5 VPO ML-093



1.7x2.5 VPO ML-101  
2x3 VPO ML-102  
3x5 VPO ML-103




1.7x2.5 VPO ML-111  
2x3 VPO ML-112  
3x5 VPO ML-113




1.7x2.5 VPO ML-121  
2x3 VPO ML-122  
3x5 VPO ML-123



1.7x2.5 VPO ML-141  
2x3 VPO ML-142  
3x5 VPO ML-143



1.7x2.5 VPO ML-151  
2x3 VPO ML-152  
3x5 VPO ML-153



1.7x2.5 VPO ML-161  
2x3 VPO ML-162  
3x5 VPO ML-163



1.7x2.5 VPO ML-171  
2x3 VPO ML-172  
3x5 VPO ML-173



1.7x2.5 VPO ML-181  
2x3 VPO ML-182  
3x5 VPO ML-183



1.7x2.5 VPO ML-191  
2x3 VPO ML-192  
3x5 VPO ML-193

ANSI Graphic Machine Labels  
All Sizes

ALL SIZES  
5 PACK

American National Standard ANSI Z535.4 2002 provides a uniform layout for safety labels and signs that is applicable to all products in all industries that may pose a safety question except safety labeling of chemicals and the transportation of dangerous goods."

# THE SIGNS OF A SAFE INDUSTRY

Electrical shock, arc flash, and arc blast are hazards associated with working on or in close proximity to energized equipment. All three types can and do occur in industrial facilities.

The three applicable regulatory standards are OSHA 29 CFR 1910 subpart S-Electrical, NFPA 70E-2000 edition, and NEC 2002.


# Arc Flash Protection Labels




- 3x5 VPO AF-651114
- 7x10 AL AF-651121
- FG AF-651122
- PL AF-651123
- VPO AF-651124
- 10x14 AL AF-651131
- FG AF-651132
- PL AF-651133
- VPO AF-651134



- 3x5 VPO AF-651214
- 7x10 AL AF-651221
- FG AF-651222
- PL AF-651223
- VPO AF-651224
- 10x14 AL AF-651231
- FG AF-651232
- PL AF-651233
- VPO AF-651234




- 3x5 VPO AF-651314
- 7x10 AL AF-651321
- FG AF-651322
- PL AF-651323
- VPO AF-651324
- 10x14 AL AF-651331
- FG AF-651332
- PL AF-651333
- VPO AF-651334



- 3x5 VPO AF-651414
- 7x10 AL AF-651421
- FG AF-651422
- PL AF-651423
- VPO AF-651424
- 10x14 AL AF-651431
- FG AF-651432
- PL AF-651433
- VPO AF-651434




Arc flash accidents and explosions cause more than 2,000 injuries per year according to the NFPA.



- 3x5 VPO AF-651714
- 7x10 AL AF-651721
- FG AF-651722
- PL AF-651723
- VPO AF-651724
- 10x14 AL AF-651731
- FG AF-651732
- PL AF-651733
- VPO AF-651734



- 3x5 VPO AF-651814
- 7x10 AL AF-651821
- FG AF-651822
- PL AF-651823
- VPO AF-651824
- 10x14 AL AF-651831
- FG AF-651832
- PL AF-651833
- VPO AF-651834




- 3x5 VPO AF-651914
- 7x10 AL AF-651921
- FG AF-651922
- PL AF-651923
- VPO AF-651924
- 10x14 AL AF-651931
- FG AF-651932
- PL AF-651933
- VPO AF-651934




- 3x5 VPO AF-652014
- 7x10 AL AF-652021
- FG AF-652022
- PL AF-652023
- VPO AF-652024
- 10x14 AL AF-652031
- FG AF-652032
- PL AF-652033
- VPO AF-652034



- 3x5 VPO AF-652114
- 7x10 AL AF-652121
- FG AF-652122
- PL AF-652123
- VPO AF-652124
- 10x14 AL AF-652131
- FG AF-652132
- PL AF-652133
- VPO AF-652134




- 3x5 VPO AF-651514
- 7x10 AL AF-651521
- FG AF-651522
- PL AF-651523
- VPO AF-651524
- 10x14 AL AF-651531
- FG AF-651532
- PL AF-651533
- VPO AF-651534



- 3x5 VPO AF-651614
- 7x10 AL AF-651621
- FG AF-651622
- PL AF-651623
- VPO AF-651624
- 10x14 AL AF-651631
- FG AF-651632
- PL AF-651633
- VPO AF-651634



4x12 VPO AF-652214



4x12 VPO AF-652314

# Authorized Personnel



- 3x5 VPO D-002114
- 7x10 AL D-002121
- FG D-002122
- PL D-002123
- VPO D-002124
- 10x14 AL D-002131
- FG D-002132
- PL D-002133
- VPO D-002134
- 14x20 AL D-002141
- PL D-002143
- VPO D-002144




- 3x5 VPO D-001014
- 7x10 AL D-001021
- FG D-001022
- PL D-001023
- VPO D-001024
- 10x14 AL D-001031
- FG D-001032
- PL D-001033
- VPO D-001034
- 14x20 AL D-001041
- PL D-001043
- VPO D-001044



- 3x5 VPO W-966014
- 7x10 AL W-966021
- FG W-966022
- PL W-966023
- VPO W-966024
- 10x14 AL W-966031
- FG W-966032
- PL W-966033
- VPO W-966034
- 14x20 AL W-966041
- PL W-966043
- VPO W-966044



- 3x5 VPO N-001314
- 7x10 AL N-001321
- FG N-001322
- PL N-001323
- VPO N-001324
- 10x14 AL N-001331
- FG N-001332
- PL N-001333
- VPO N-001334
- 14x20 AL N-001341
- PL N-001343
- VPO N-001344



- 3x5 VPO N-001514
- 7x10 AL N-001521
- FG N-001522
- PL N-001523
- VPO N-001524
- 10x14 AL N-001531
- FG N-001532
- PL N-001533
- VPO N-001534
- 14x20 AL N-001541
- PL N-001543
- VPO N-001544



- 3x5 VPO G-000314
- 7x10 AL G-000321
- FG G-000322
- PL G-000323
- VPO G-000324
- 10x14 AL G-000331
- FG G-000332
- PL G-000333
- VPO G-000334
- 14x20 AL G-000341
- PL G-000343
- VPO G-000344

• If You Don't See It, We Can Make It!

• Custom Jobs Our Specialty...Please Call For A Quote!

# Asbestos & Lead Abatement

*THE SIGNS OF A SAFE INDUSTRY*

OSHA §1926.1101(k)(7)(i) states "Warning signs that demarcate the regulated area shall be provided and displayed at each location where a regulated area is required to be established by paragraph (e) of this section. Signs shall be posted at such a distance from such a location that an employee may read the signs and take necessary protective steps before entering the area marked by the signs."


## Asbestos Labels Self-adhesive paper labels 3" x 5" • 500 per roll




SAHL-12




SAHL-13



SL-9902



SL-9903



SL-37



SL-36



SL-9901



SL-9904



SL-9906



SL-9905

## Asbestos and Lead Abatement Signs



### Barricade Tape

3 mil thick • 3" x 1000' Rolls

SBT-46 - DANGER ASBESTOS (red/black copy)  
 SBT-47 - DANGER ASBESTOS (as shown white w/cautionary information)

ASBESTOS  
 CANCER AND LUNG DISEASE HAZARD  
 AUTHORIZED PERSONNEL ONLY  
 RESPIRATORS AND  
 PROTECTIVE CLOTHING  
 ARE REQUIRED IN THIS AREA

See page 120 for more barricade tapes

Material	Sign Type	Message	Size	Material	Sign Type	Message	Size	Material	Sign Type	Message	Size	Material	Sign Type	Message	Size
3x5 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450114	3x5 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450614	3x5 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000914	3x5 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001914
7x10 AL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450121	7x10 AL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450621	7x10 AL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000921	7x10 AL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001921
7x10 FG	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450122	7x10 FG	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450622	7x10 FG	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000922	7x10 FG	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001922
7x10 PL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450123	7x10 PL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450623	7x10 PL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000923	7x10 PL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001923
7x10 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450124	7x10 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450624	7x10 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000924	7x10 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001924
10x14 AL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450131	10x14 AL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450631	10x14 AL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000931	10x14 AL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001931
10x14 FG	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450132	10x14 FG	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450632	10x14 FG	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000932	10x14 FG	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001932
10x14 PL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450133	10x14 PL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450633	10x14 PL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000933	10x14 PL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001933
10x14 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450134	10x14 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450634	10x14 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000934	10x14 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001934
14x20 AL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450141	14x20 AL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450641	14x20 AL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000941	14x20 AL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001941
14x20 PL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450143	14x20 PL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450643	14x20 PL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000943	14x20 PL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001943
14x20 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450144	14x20 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450644	14x20 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000944	14x20 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001944
3x5 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450114	3x5 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450614	3x5 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000914	3x5 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001914
7x10 AL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450121	7x10 AL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450621	7x10 AL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000921	7x10 AL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001921
7x10 FG	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450122	7x10 FG	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450622	7x10 FG	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000922	7x10 FG	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001922
7x10 PL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450123	7x10 PL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450623	7x10 PL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000923	7x10 PL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001923
7x10 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450124	7x10 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450624	7x10 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000924	7x10 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001924
10x14 AL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450131	10x14 AL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450631	10x14 AL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000931	10x14 AL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001931
10x14 FG	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450132	10x14 FG	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450632	10x14 FG	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000932	10x14 FG	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001932
10x14 PL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450133	10x14 PL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450633	10x14 PL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000933	10x14 PL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001933
10x14 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450134	10x14 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450634	10x14 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000934	10x14 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001934
14x20 AL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450141	14x20 AL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450641	14x20 AL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000941	14x20 AL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001941
14x20 PL	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450143	14x20 PL	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450643	14x20 PL	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000943	14x20 PL	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001943
14x20 VPO	WARNING	LEAD WORK AREA POISON NO SMOKING OR EATING	W-450144	14x20 VPO	CAUTION	LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED	C-450644	14x20 VPO	CAUTION	ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT	C-000944	14x20 VPO	DANGER	ASBESTOS CANCER AND LUNG DISEASE HAZARD AUTHORIZED PERSONNEL ONLY RESPIRATORS AND PROTECTIVE CLOTHING ARE REQUIRED IN THIS AREA	D-001944

### Paper Signs 100 PER PACK

PS-01 (11" x 17")  
PS-04 (14" x 20")


PS-02 11" X 17"

SPANISH

PS-03 11" x 17"

### Asbestos Floor Sign

These signs are printed on both sides for two-way traffic flow. Floor Stand Signs are weather resistant for indoor/outdoor usage. Each sign is printed with two messages. Reverse the sign to display the second message. Sturdy 12"x20" (30 x 51 cm) corrugated polyethylene. Weight 1 lb. (.45kg)



FFS-12

See page 50 for more floor stands

- If You Don't See It, We Can Make It!
- Custom Jobs Our Specialty...Please Call For A Quote!

# CAUTION

OSHA§1910.145(c)(2)(i) states "Caution signs shall be used only to warn against potential hazards or to Caution against unsafe practices." (ii) states "All employees shall be instructed that Caution signs indicate a possible hazard against which proper precaution should be taken."  
This heading should not be used when there is a possibility of death or serious injury.

## THE SIGNS OF A SAFE INDUSTRY

MATERIALS



**CAUTION**  
**ACID**

3x5 VPO C-000114  
7x10 AL C-000121  
FG C-000122  
PL C-000123  
VPO C-000124  
10x14 AL C-000131  
FG C-000132  
PL C-000133  
VPO C-000134  
14x20 AL C-000141  
PL C-000143  
VPO C-000144

**CAUTION**  
**ACID BE CAREFUL**

3x5 VPO C-000214  
7x10 AL C-000221  
FG C-000222  
PL C-000223  
VPO C-000224  
10x14 AL C-000231  
FG C-000232  
PL C-000233  
VPO C-000234  
14x20 AL C-000241  
PL C-000243  
VPO C-000244

**CAUTION**  
AREA IN FRONT OF ELECTRICAL PANEL MUST BE KEPT CLEAR FOR 36 INCHES OSHA REGULATIONS

3x5 VPO C-000614  
7x10 AL C-000621  
FG C-000622  
PL C-000623  
VPO C-000624  
10x14 AL C-000631  
FG C-000632  
PL C-000633  
VPO C-000634  
14x20 AL C-000641  
PL C-000643  
VPO C-000644

**CAUTION**  
ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT

3x5 VPO C-000914  
7x10 AL C-000921  
FG C-000922  
PL C-000923  
VPO C-000924  
10x14 AL C-000931  
FG C-000932  
PL C-000933  
VPO C-000934  
14x20 AL C-000941  
PL C-000943  
VPO C-000944

**CAUTION**  
**ATTACH GROUNDING WIRE CLIPS**

3x5 VPO C-001114  
7x10 AL C-001121  
FG C-001122  
PL C-001123  
VPO C-001124  
10x14 AL C-001131  
FG C-001132  
PL C-001133  
VPO C-001134  
14x20 AL C-001141  
PL C-001143  
VPO C-001144

**CAUTION**  
AUTOMATIC EQUIPMENT WILL START AT ANY TIME

3x5 VPO C-001214  
7x10 AL C-001221  
FG C-001222  
PL C-001223  
VPO C-001224  
10x14 AL C-001231  
FG C-001232  
PL C-001233  
VPO C-001234  
14x20 AL C-001241  
PL C-001243  
VPO C-001244

**CAUTION**  
BATTERY CHARGING STATION NO SMOKING OR OPEN FLAMES

3x5 VPO C-050114  
7x10 AL C-050121  
FG C-050122  
PL C-050123  
VPO C-050124  
10x14 AL C-050131  
FG C-050132  
PL C-050133  
VPO C-050134  
14x20 AL C-050141  
PL C-050143  
VPO C-050144

**CAUTION**  
BEFORE ENTERING TEST FOR EXPLOSIVE ATMOSPHERE TEST FOR OXYGEN DEFICIENCY SUPPLY FRESH AIR TO WORK AREA

3x5 VPO C-050314  
7x10 AL C-050321  
FG C-050322  
PL C-050323  
VPO C-050324  
10x14 AL C-050331  
FG C-050332  
PL C-050333  
VPO C-050334  
14x20 AL C-050341  
PL C-050343  
VPO C-050344

**CAUTION**  
BEFORE PROCEEDING WITH REPAIR WORK ALL SOURCES OF POWER TO THE MACHINE MUST BE TAGGED OUT AND/OR SECURED WITH A LOCKING DEVICE

3x5 VPO C-050414  
7x10 AL C-050421  
FG C-050422  
PL C-050423  
VPO C-050424  
10x14 AL C-050431  
FG C-050432  
PL C-050433  
VPO C-050434  
14x20 AL C-050441  
PL C-050443  
VPO C-050444

**CAUTION**  
BEFORE YOU START LOCKOUT FOR SAFETY

3x5 VPO C-050514  
7x10 AL C-050521  
FG C-050522  
PL C-050523  
VPO C-050524  
10x14 AL C-050531  
FG C-050532  
PL C-050533  
VPO C-050534  
14x20 AL C-050541  
PL C-050543  
VPO C-050544

**CAUTION**  
**BEND KNEES WHEN LIFTING**

3x5 VPO C-050614  
7x10 AL C-050621  
FG C-050622  
PL C-050623  
VPO C-050624  
10x14 AL C-050631  
FG C-050632  
PL C-050633  
VPO C-050634  
14x20 AL C-050641  
PL C-050643  
VPO C-050644

**CAUTION**  
**BEWARE OF FALLING OBJECTS**

3x5 VPO C-050714  
7x10 AL C-050721  
FG C-050722  
PL C-050723  
VPO C-050724  
10x14 AL C-050731  
FG C-050732  
PL C-050733  
VPO C-050734  
14x20 AL C-050741  
PL C-050743  
VPO C-050744

**CAUTION**  
**BUMP HAT REQUIRED**

3x5 VPO C-050814  
7x10 AL C-050821  
FG C-050822  
PL C-050823  
VPO C-050824  
10x14 AL C-050831  
FG C-050832  
PL C-050833  
VPO C-050834  
14x20 AL C-050841  
PL C-050843  
VPO C-050844

**CAUTION**  
**BURIED GAS LINE**

3x5 VPO C-050914  
7x10 AL C-050921  
FG C-050922  
PL C-050923  
VPO C-050924  
10x14 AL C-050931  
FG C-050932  
PL C-050933  
VPO C-050934  
14x20 AL C-050941  
PL C-050943  
VPO C-050944

**CAUTION**  
**BURIED WATER LINE**

3x5 VPO C-051114  
7x10 AL C-051121  
FG C-051122  
PL C-051123  
VPO C-051124  
10x14 AL C-051131  
FG C-051132  
PL C-051133  
VPO C-051134  
14x20 AL C-051141  
PL C-051143  
VPO C-051144

**CAUTION**

3x5 VPO C-080614  
7x10 AL C-080621  
FG C-080622  
PL C-080623  
VPO C-080624  
10x14 AL C-080631  
FG C-080632  
PL C-080633  
VPO C-080634  
14x20 AL C-080641  
PL C-080643  
VPO C-080644

**CAUTION**  
CARBON MONOXIDE MAY BE PRESENT

3x5 VPO C-080214  
7x10 AL C-080221  
FG C-080222  
PL C-080223  
VPO C-080224  
10x14 AL C-080231  
FG C-080232  
PL C-080233  
VPO C-080234  
14x20 AL C-080241  
PL C-080243  
VPO C-080244

**CAUTION**  
**CAUSTIC**

3x5 VPO C-080314  
7x10 AL C-080321  
FG C-080322  
PL C-080323  
VPO C-080324  
10x14 AL C-080331  
FG C-080332  
PL C-080333  
VPO C-080334  
14x20 AL C-080341  
PL C-080343  
VPO C-080344

**CAUTION**  
CAUSTIC SODA AVOID SKIN OR EYE CONTACT AVOID INHALATION OR INGESTION CAN CAUSE SEVERE BURNS WEAR PROTECTIVE CLOTHING WHEN WORKING WITH CAUSTIC SODA IF SKIN OR EYES ARE CONTACTED FLUSH WITH WATER FOR 15 MIN.

3x5 VPO C-080414  
7x10 AL C-080421  
FG C-080422  
PL C-080423  
VPO C-080424  
10x14 AL C-080431  
FG C-080432  
PL C-080433  
VPO C-080434  
14x20 AL C-080441  
PL C-080443  
VPO C-080444

**CAUTION**  
**CHAIN GAS CYLINDERS**

3x5 VPO C-080814  
7x10 AL C-080821  
FG C-080822  
PL C-080823  
VPO C-080824  
10x14 AL C-080831  
FG C-080832  
PL C-080833  
VPO C-080834  
14x20 AL C-080841  
PL C-080843  
VPO C-080844

**CAUTION**  
**CHEMICAL GOGGLE AREA**

3x5 VPO C-080914  
7x10 AL C-080921  
FG C-080922  
PL C-080923  
VPO C-080924  
10x14 AL C-080931  
FG C-080932  
PL C-080933  
VPO C-080934  
14x20 AL C-080941  
PL C-080943  
VPO C-080944

**CAUTION**  
**CHEMICALS**

3x5 VPO C-081114  
7x10 AL C-081121  
FG C-081122  
PL C-081123  
VPO C-081124  
10x14 AL C-081131  
FG C-081132  
PL C-081133  
VPO C-081134  
14x20 AL C-081141  
PL C-081143  
VPO C-081144

**CAUTION**  
**CHLORINE AREA**

3x5 VPO C-081214  
7x10 AL C-081221  
FG C-081222  
PL C-081223  
VPO C-081224  
10x14 AL C-081231  
FG C-081232  
PL C-081233  
VPO C-081234  
14x20 AL C-081241  
PL C-081243  
VPO C-081244

**CAUTION**  
CHLORINE AVOID INHALATION AND SKIN OR EYE CONTACT INHALATION WILL CAUSE SHORTNESS OF BREATH AND NAUSEA A NIOSH/MSHA APPROVED CHEMICAL CARTRIDGE TYPE ESCAPE RESPIRATOR SHOULD BE CARRIED AT ALL TIMES WHEN HANDLING CHLORINE

3x5 VPO C-081314  
7x10 AL C-081321  
FG C-081322  
PL C-081323  
VPO C-081324  
10x14 AL C-081331  
FG C-081332  
PL C-081333  
VPO C-081334  
14x20 AL C-081341  
PL C-081343  
VPO C-081344

**CAUTION**  
CLASS II HELIUM NEON LASER DO NOT STARE INTO BEAM

3x5 VPO C-081414  
7x10 AL C-081421  
FG C-081422  
PL C-081423  
VPO C-081424  
10x14 AL C-081431  
FG C-081432  
PL C-081433  
VPO C-081434  
14x20 AL C-081441  
PL C-081443  
VPO C-081444

**CAUTION**  
**CLEARANCE**  
\_\_\_ FT. \_\_\_ IN.

3x5 VPO C-081514  
7x10 AL C-081521  
FG C-081522  
PL C-081523  
VPO C-081524  
10x14 AL C-081531  
FG C-081532  
PL C-081533  
VPO C-081534  
14x20 AL C-081541  
PL C-081543  
VPO C-081544

**CAUTION**  
**CLOSE CLEARANCE**

3x5 VPO C-081614  
7x10 AL C-081621  
FG C-081622  
PL C-081623  
VPO C-081624  
10x14 AL C-081631  
FG C-081632  
PL C-081633  
VPO C-081634  
14x20 AL C-081641  
PL C-081643  
VPO C-081644

**CAUTION**  
CLOTHING CONTAMINATED WITH LEAD DO NOT REMOVE DUST BY BLOWING

3x5 VPO C-081714  
7x10 AL C-081721  
FG C-081722  
PL C-081723  
VPO C-081724  
10x14 AL C-081731  
FG C-081732  
PL C-081733  
VPO C-081734  
14x20 AL C-081741  
PL C-081743  
VPO C-081744

# THE SIGNS OF A SAFE INDUSTRY



# CAUTION

<p><b>CAUTION</b></p> <p>CLOTHING CONTAMINATED WITH LEAD DO NOT REMOVE DUST BY BLOWING OR SHAKING DISPOSE OF LEAD CONTAMINATED WASH WATER IN ACCORDANCE WITH APPLICABLE LOCAL STATE OR FEDERAL REGULATIONS</p> <p>3x5 VPO C-081814 7x10 AL C-081821 FG C-081822 PL C-081823 VPO C-081824 10x14 AL C-081831 FG C-081832 PL C-081833 VPO C-081834 14x20 AL C-081841 PL C-081843 VPO C-081844</p>	<p><b>CAUTION</b></p> <p><b>COMPRESSED AIR</b></p> <p>3x5 VPO C-081914 7x10 AL C-081921 FG C-081922 PL C-081923 VPO C-081924 10x14 AL C-081931 FG C-081932 PL C-081933 VPO C-081934 14x20 AL C-081941 PL C-081943 VPO C-081944</p>	<p><b>CAUTION</b></p> <p><b>CONFINED SPACE</b></p> <p>3x5 VPO C-082014 7x10 AL C-082021 FG C-082022 PL C-082023 VPO C-082024 10x14 AL C-082031 FG C-082032 PL C-082033 VPO C-082034 14x20 AL C-082041 PL C-082043 VPO C-082044</p>	<p><b>CAUTION</b></p> <p><b>CONFINED SPACE</b> DO NOT ENTER WITHOUT OBTAINING PERMIT NO. _____</p> <p>3x5 VPO C-082214 7x10 AL C-082221 FG C-082222 PL C-082223 VPO C-082224 10x14 AL C-082231 FG C-082232 PL C-082233 VPO C-082234 14x20 AL C-082241 PL C-082243 VPO C-082244</p>	<p><b>CAUTION</b></p> <p><b>CONFINED SPACE</b> ENTER BY PERMIT ONLY</p> <p>3x5 VPO C-082314 7x10 AL C-082321 FG C-082322 PL C-082323 VPO C-082324 10x14 AL C-082331 FG C-082332 PL C-082333 VPO C-082334 14x20 AL C-082341 PL C-082343 VPO C-082344</p>	<p><b>CAUTION</b></p> <p><b>CONFINED SPACE</b> ENTRY PERMIT REQUIRED CALL SECURITY</p> <p>3x5 VPO C-082414 7x10 AL C-082421 FG C-082422 PL C-082423 VPO C-082424 10x14 AL C-082431 FG C-082432 PL C-082433 VPO C-082434 14x20 AL C-082441 PL C-082443 VPO C-082444</p>	<p><b>CAUTION</b></p> <p><b>CONFINED SPACE</b> ENTRY PERMIT REQUIRED CONTACT YOUR SUPERVISOR</p> <p>3x5 VPO C-082514 7x10 AL C-082521 FG C-082522 PL C-082523 VPO C-082524 10x14 AL C-082531 FG C-082532 PL C-082533 VPO C-082534 14x20 AL C-082541 PL C-082543 VPO C-082544</p>
--	--	--	--	---	--	--

<p><b>CAUTION</b></p> <p><b>CONFINED SPACE</b> NO. _____ ENTRY PERMIT REQUIRED CALL _____</p> <p>3x5 VPO C-082614 7x10 AL C-082621 FG C-082622 PL C-082623 VPO C-082624 10x14 AL C-082631 FG C-082632 PL C-082633 VPO C-082634 14x20 AL C-082641 PL C-082643 VPO C-082644</p>	<p><b>CAUTION</b></p> <p><b>CONGESTED AISLE</b></p> <p>3x5 VPO C-082714 7x10 AL C-082721 FG C-082722 PL C-082723 VPO C-082724 10x14 AL C-082731 FG C-082732 PL C-082733 VPO C-082734 14x20 AL C-082741 PL C-082743 VPO C-082744</p>	<p><b>CAUTION</b></p> <p><b>CONGESTED AREA</b></p> <p>3x5 VPO C-082814 7x10 AL C-082821 FG C-082822 PL C-082823 VPO C-082824 10x14 AL C-082831 FG C-082832 PL C-082833 VPO C-082834 14x20 AL C-082841 PL C-082843 VPO C-082844</p>	<p><b>CAUTION</b></p> <p><b>CONNECT GROUND WIRE</b> BEFORE USING</p> <p>3x5 VPO C-082914 7x10 AL C-082921 FG C-082922 PL C-082923 VPO C-082924 10x14 AL C-082931 FG C-082932 PL C-082933 VPO C-082934 14x20 AL C-082941 PL C-082943 VPO C-082944</p>	<p><b>CAUTION</b></p> <p><b>CONSTRUCTION AREA</b></p> <p>3x5 VPO C-083014 7x10 AL C-083021 FG C-083022 PL C-083023 VPO C-083024 10x14 AL C-083031 FG C-083032 PL C-083033 VPO C-083034 14x20 AL C-083041 PL C-083043 VPO C-083044</p>	<p><b>CAUTION</b></p> <p>CONTAINS ASBESTOS FIBERS AVOID CREATING DUST BREATHING ASBESTOS DUST MAY CAUSE SERIOUS BODILY HARM</p> <p>3x5 VPO C-083114 7x10 AL C-083121 FG C-083122 PL C-083123 VPO C-083124 10x14 AL C-083131 FG C-083132 PL C-083133 VPO C-083134 14x20 AL C-083141 PL C-083143 VPO C-083144</p>	<p><b>CAUTION</b></p> <p><b>CONTAINS CORROSIVE LIQUID</b></p> <p>3x5 VPO C-083214 7x10 AL C-083221 FG C-083222 PL C-083223 VPO C-083224 10x14 AL C-083231 FG C-083232 PL C-083233 VPO C-083234 14x20 AL C-083241 PL C-083243 VPO C-083244</p>
---	---	--	--	---	---	---

<p><b>CAUTION</b></p> <p>CONTAINS ETHYLENE OXIDE CANCER AND REPRODUCTIVE HAZARD AVOID BREATHING VAPORS</p> <p>3x5 VPO C-083314 7x10 AL C-083321 FG C-083322 PL C-083323 VPO C-083324 10x14 AL C-083331 FG C-083332 PL C-083333 VPO C-083334 14x20 AL C-083341 PL C-083343 VPO C-083344</p>	<p><b>CAUTION</b></p> <p>CONTAINS HAZARDOUS MATERIAL SEE MSDS FILE</p> <p>3x5 VPO C-083414 7x10 AL C-083421 FG C-083422 PL C-083423 VPO C-083424 10x14 AL C-083431 FG C-083432 PL C-083433 VPO C-083434 14x20 AL C-083441 PL C-083443 VPO C-083444</p>	<p><b>CAUTION</b></p> <p>CONTAINS PCB CANCER HAZARD</p> <p>3x5 VPO C-083514 7x10 AL C-083521 FG C-083522 PL C-083523 VPO C-083524 10x14 AL C-083531 FG C-083532 PL C-083533 VPO C-083534 14x20 AL C-083541 PL C-083543 VPO C-083544</p>	<p><b>CAUTION</b></p> <p><b>CONVEYOR MAY START WITHOUT WARNING</b></p> <p>3x5 VPO C-083614 7x10 AL C-083621 FG C-083622 PL C-083623 VPO C-083624 10x14 AL C-083631 FG C-083632 PL C-083633 VPO C-083634 14x20 AL C-083641 PL C-083643 VPO C-083644</p>	<p><b>CAUTION</b></p> <p><b>CORROSIVE MATERIAL IN USE</b></p> <p>3x5 VPO C-083714 7x10 AL C-083721 FG C-083722 PL C-083723 VPO C-083724 10x14 AL C-083731 FG C-083732 PL C-083733 VPO C-083734 14x20 AL C-083741 PL C-083743 VPO C-083744</p>	<p><b>CAUTION</b></p> <p><b>CUTTING AND WELDING PERMIT REQUIRED IN THIS AREA</b></p> <p>3x5 VPO C-083914 7x10 AL C-083921 FG C-083922 PL C-083923 VPO C-083924 10x14 AL C-083931 FG C-083932 PL C-083933 VPO C-083934 14x20 AL C-083941 PL C-083943 VPO C-083944</p>	<p><b>CAUTION</b></p> <p><b>DEPOSIT MATCHES AND ALL SMOKING MATERIAL IN THIS RECEPTACLE</b></p> <p>3x5 VPO C-110114 7x10 AL C-110121 FG C-110122 PL C-110123 VPO C-110124 10x14 AL C-110131 FG C-110132 PL C-110133 VPO C-110134 14x20 AL C-110141 PL C-110143 VPO C-110144</p>
--	--	---	--	---	--	---

<p><b>CAUTION</b></p> <p><b>DISCONNECT POWER BEFORE SERVICING</b></p> <p>3x5 VPO C-110314 7x10 AL C-110321 FG C-110322 PL C-110323 VPO C-110324 10x14 AL C-110331 FG C-110332 PL C-110333 VPO C-110334 14x20 AL C-110341 PL C-110343 VPO C-110344</p>	<p><b>CAUTION</b></p> <p><b>DO NOT ENTER</b></p> <p>3x5 VPO C-110414 7x10 AL C-110421 FG C-110422 PL C-110423 VPO C-110424 10x14 AL C-110431 FG C-110432 PL C-110433 VPO C-110434 14x20 AL C-110441 PL C-110443 VPO C-110444</p>	<p><b>CAUTION</b></p> <p>DO NOT BACK THIS VEHICLE UNLESS YOU ARE SURE IT IS SAFE AND CLEAR</p> <p>3x5 VPO C-110514 7x10 AL C-110521 FG C-110522 PL C-110523 VPO C-110524 10x14 AL C-110531 FG C-110532 PL C-110533 VPO C-110534 14x20 AL C-110541 PL C-110543 VPO C-110544</p>	<p><b>CAUTION</b></p> <p>DO NOT ENTER THIS SHOP WITHOUT EYE PROTECTION</p> <p>3x5 VPO C-110914 7x10 AL C-110921 FG C-110922 PL C-110923 VPO C-110924 10x14 AL C-110931 FG C-110932 PL C-110933 VPO C-110934 14x20 AL C-110941 PL C-110943 VPO C-110944</p>	<p><b>CAUTION</b></p> <p>DO NOT ENTER WITHOUT AIR PAC WHEN CHLORINE ALARM IS ON</p> <p>3x5 VPO C-111014 7x10 AL C-111021 FG C-111022 PL C-111023 VPO C-111024 10x14 AL C-111031 FG C-111032 PL C-111033 VPO C-111034 14x20 AL C-111041 PL C-111043 VPO C-111044</p>	<p><b>CAUTION</b></p> <p>DO NOT ENTER WHEN RED LIGHT IS FLASHING</p> <p>3x5 VPO C-111114 7x10 AL C-111121 FG C-111122 PL C-111123 VPO C-111124 10x14 AL C-111131 FG C-111132 PL C-111133 VPO C-111134 14x20 AL C-111141 PL C-111143 VPO C-111144</p>	<p><b>CAUTION</b></p> <p>DO NOT ENTER WHILE MACHINERY IN MOTION</p> <p>3x5 VPO C-111214 7x10 AL C-111221 FG C-111222 PL C-111223 VPO C-111224 10x14 AL C-111231 FG C-111232 PL C-111233 VPO C-111234 14x20 AL C-111241 PL C-111243 VPO C-111244</p>
---	--	--	--	---	--	---

• If You Don't See It, We Can Make It!

• Custom Jobs Our Specialty...Please Call For A Quote!

# CAUTION

## THE SIGNS OF A SAFE INDUSTRY



**CAUTION**  
DO NOT ENTER  
WITHOUT A  
CONFINED SPACE  
PERMIT

3x5 VPO C-111514  
7x10 AL C-111521  
FG C-111522  
PL C-111523  
VPO C-111524  
10x14 AL C-111531  
FG C-111532  
PL C-111533  
VPO C-111534  
14x20 AL C-111541  
PL C-111543  
VPO C-111544

**CAUTION**  
DO NOT ENTER  
WITHOUT EYE  
PROTECTION

3x5 VPO C-111614  
7x10 AL C-111621  
FG C-111622  
PL C-111623  
VPO C-111624  
10x14 AL C-111631  
FG C-111632  
PL C-111633  
VPO C-111634  
14x20 AL C-111641  
PL C-111643  
VPO C-111644

**CAUTION**  
DO NOT GRIND IF  
CLEARANCE BETWEEN  
WHEEL AND TOOL REST  
IS MORE THAN 1/16 INCH

3x5 VPO C-111814  
7x10 AL C-111821  
FG C-111822  
PL C-111823  
VPO C-111824  
10x14 AL C-111831  
FG C-111832  
PL C-111833  
VPO C-111834  
14x20 AL C-111841  
PL C-111843  
VPO C-111844

**CAUTION**  
DO NOT GRIND IF  
CLEARANCE BETWEEN  
WHEEL AND TOOL REST IS  
MORE THAN 1/8 INCH

3x5 VPO C-111914  
7x10 AL C-111921  
FG C-111922  
PL C-111923  
VPO C-111924  
10x14 AL C-111931  
FG C-111932  
PL C-111933  
VPO C-111934  
14x20 AL C-111941  
PL C-111943  
VPO C-111944

**CAUTION**  
DO NOT OPERATE MACHINERY  
WITHOUT GUARDS  
DO NOT REMOVE GUARDS,  
CLEAN, OIL OR REPAIR  
MACHINERY  
WHILE IN MOTION

3x5 VPO C-112114  
7x10 AL C-112121  
FG C-112122  
PL C-112123  
VPO C-112124  
10x14 AL C-112131  
FG C-112132  
PL C-112133  
VPO C-112134  
14x20 AL C-112141  
PL C-112143  
VPO C-112144

**CAUTION**  
DO NOT OPERATE  
THIS EQUIPMENT  
WITHOUT  
EAR PROTECTION

3x5 VPO C-112214  
7x10 AL C-112221  
FG C-112222  
PL C-112223  
VPO C-112224  
10x14 AL C-112231  
FG C-112232  
PL C-112233  
VPO C-112234  
14x20 AL C-112241  
PL C-112243  
VPO C-112244

**CAUTION**  
DO NOT OPERATE  
THIS MACHINE  
WITHOUT  
EYE PROTECTION

3x5 VPO C-112414  
7x10 AL C-112421  
FG C-112422  
PL C-112423  
VPO C-112424  
10x14 AL C-112431  
FG C-112432  
PL C-112433  
VPO C-112434  
14x20 AL C-112441  
PL C-112443  
VPO C-112444

**CAUTION**  
DO NOT OPERATE  
THIS MACHINE  
WITHOUT  
GUARDS IN PLACE

3x5 VPO C-112614  
7x10 AL C-112621  
FG C-112622  
PL C-112623  
VPO C-112624  
10x14 AL C-112631  
FG C-112632  
PL C-112633  
VPO C-112634  
14x20 AL C-112641  
PL C-112643  
VPO C-112644

**CAUTION**  
DO NOT  
OPERATE  
WITHOUT GUARD

3x5 VPO C-112714  
7x10 AL C-112721  
FG C-112722  
PL C-112723  
VPO C-112724  
10x14 AL C-112731  
FG C-112732  
PL C-112733  
VPO C-112734  
14x20 AL C-112741  
PL C-112743  
VPO C-112744

**CAUTION**  
DO NOT STARE INTO  
BEAM HELIUM NEON  
LASER

3x5 VPO C-113014  
7x10 AL C-113021  
FG C-113022  
PL C-113023  
VPO C-113024  
10x14 AL C-113031  
FG C-113032  
PL C-113033  
VPO C-113034  
14x20 AL C-113041  
PL C-113043  
VPO C-113044

**CAUTION**  
DO NOT STARE  
INTO BEAM  
LASER IN USE

3x5 VPO C-113114  
7x10 AL C-113121  
FG C-113122  
PL C-113123  
VPO C-113124  
10x14 AL C-113131  
FG C-113132  
PL C-113133  
VPO C-113134  
14x20 AL C-113141  
PL C-113143  
VPO C-113144

**CAUTION**  
DO NOT TALK TO  
OPERATOR WHILE  
MACHINE IS IN  
MOTION

3x5 VPO C-113214  
7x10 AL C-113221  
FG C-113222  
PL C-113223  
VPO C-113224  
10x14 AL C-113231  
FG C-113232  
PL C-113233  
VPO C-113234  
14x20 AL C-113241  
PL C-113243  
VPO C-113244

**CAUTION**  
DO NOT THROW  
MATCHES, RUBBISH,  
CIGARETTE OR CIGAR  
STUBS IN URINALS

3x5 VPO C-113314  
7x10 AL C-113321  
FG C-113322  
PL C-113323  
VPO C-113324  
10x14 AL C-113331  
FG C-113332  
PL C-113333  
VPO C-113334  
14x20 AL C-113341  
PL C-113343  
VPO C-113344

**CAUTION**  
DO NOT USE  
COMPRESSED AIR  
TO BLOW OFF  
CLOTHING

3x5 VPO C-113414  
7x10 AL C-113421  
FG C-113422  
PL C-113423  
VPO C-113424  
10x14 AL C-113431  
FG C-113432  
PL C-113433  
VPO C-113434  
14x20 AL C-113441  
PL C-113443  
VPO C-113444

**CAUTION**  
DO NOT USE  
NEAR ELECTRICAL  
EQUIPMENT

3x5 VPO C-113514  
7x10 AL C-113521  
FG C-113522  
PL C-113523  
VPO C-113524  
10x14 AL C-113531  
FG C-113532  
PL C-113533  
VPO C-113534  
14x20 AL C-113541  
PL C-113543  
VPO C-113544

**CAUTION**  
DO NOT USE  
ON ELECTRICAL  
FIRES

3x5 VPO C-113614  
7x10 AL C-113621  
FG C-113622  
PL C-113623  
VPO C-113624  
10x14 AL C-113631  
FG C-113632  
PL C-113633  
VPO C-113634  
14x20 AL C-113641  
PL C-113643  
VPO C-113644

**CAUTION**  
DO NOT  
WALK ON  
CONVEYORS

3x5 VPO C-113714  
7x10 AL C-113721  
FG C-113722  
PL C-113723  
VPO C-113724  
10x14 AL C-113731  
FG C-113732  
PL C-113733  
VPO C-113734  
14x20 AL C-113741  
PL C-113743  
VPO C-113744

**CAUTION**  
DO NOT WEAR  
GLOVES WHILE  
OPERATING  
THIS MACHINE

3x5 VPO C-113814  
7x10 AL C-113821  
FG C-113822  
PL C-113823  
VPO C-113824  
10x14 AL C-113831  
FG C-113832  
PL C-113833  
VPO C-113834  
14x20 AL C-113841  
PL C-113843  
VPO C-113844

**CAUTION**  
DOCK  
SLIPPERY  
WHEN WET

3x5 VPO C-113914  
7x10 AL C-113921  
FG C-113922  
PL C-113923  
VPO C-113924  
10x14 AL C-113931  
FG C-113932  
PL C-113933  
VPO C-113934  
14x20 AL C-113941  
PL C-113943  
VPO C-113944

**CAUTION**  
DON'T CLEAN, OIL,  
OR REPAIR MACHINERY  
WHILE IN MOTION

3x5 VPO C-114014  
7x10 AL C-114021  
FG C-114022  
PL C-114023  
VPO C-114024  
10x14 AL C-114031  
FG C-114032  
PL C-114033  
VPO C-114034  
14x20 AL C-114041  
PL C-114043  
VPO C-114044

**CAUTION**  
DON'T START  
OUT OF  
ORDER

3x5 VPO C-114214  
7x10 AL C-114221  
FG C-114222  
PL C-114223  
VPO C-114224  
10x14 AL C-114231  
FG C-114232  
PL C-114233  
VPO C-114234  
14x20 AL C-114241  
PL C-114243  
VPO C-114244

**CAUTION**  
DOOR MAY  
CLOSE SUDDENLY  
WITHOUT WARNING

3x5 VPO C-114314  
7x10 AL C-114321  
FG C-114322  
PL C-114323  
VPO C-114324  
10x14 AL C-114331  
FG C-114332  
PL C-114333  
VPO C-114334  
14x20 AL C-114341  
PL C-114343  
VPO C-114344

**CAUTION**  
DOOR OPENS  
INWARD

3x5 VPO C-114514  
7x10 AL C-114521  
FG C-114522  
PL C-114523  
VPO C-114524  
10x14 AL C-114531  
FG C-114532  
PL C-114533  
VPO C-114534  
14x20 AL C-114541  
PL C-114543  
VPO C-114544

**CAUTION**  
DOOR OPENS  
OUTWARD

3x5 VPO C-114414  
7x10 AL C-114421  
FG C-114422  
PL C-114423  
VPO C-114424  
10x14 AL C-114431  
FG C-114432  
PL C-114433  
VPO C-114434  
14x20 AL C-114441  
PL C-114443  
VPO C-114444

**CAUTION**  
EAR AND EYE  
PROTECTION  
AREA

3x5 VPO C-160114  
7x10 AL C-160121  
FG C-160122  
PL C-160123  
VPO C-160124  
10x14 AL C-160131  
FG C-160132  
PL C-160133  
VPO C-160134  
14x20 AL C-160141  
PL C-160143  
VPO C-160144

**CAUTION**  
EAR PLUGS  
REQUIRED IN  
THIS AREA

3x5 VPO C-161214  
7x10 AL C-161221  
FG C-161222  
PL C-161223  
VPO C-161224  
10x14 AL C-161231  
FG C-161232  
PL C-161233  
VPO C-161234  
14x20 AL C-161241  
PL C-161243  
VPO C-161244

**CAUTION**  
EAR  
PROTECTION  
AREA

3x5 VPO C-160214  
7x10 AL C-160221  
FG C-160222  
PL C-160223  
VPO C-160224  
10x14 AL C-160231  
FG C-160232  
PL C-160233  
VPO C-160234  
14x20 AL C-160241  
PL C-160243  
VPO C-160244

**CAUTION**  
EAR PROTECTION  
MUST BE WORN  
IN THIS AREA

3x5 VPO C-160414  
7x10 AL C-160421  
FG C-160422  
PL C-160423  
VPO C-160424  
10x14 AL C-160431  
FG C-160432  
PL C-160433  
VPO C-160434  
14x20 AL C-160441  
PL C-160443  
VPO C-160444

# THE SIGNS OF A SAFE INDUSTRY



<p><b>CAUTION</b></p> <p>EAR PROTECTION MUST BE WORN WHILE WORKING ON THIS OPERATION</p> <p>3x5 VPO C-160514 7x10 AL C-160521 FG C-160522 PL C-160523 VPO C-160524</p> <p>10x14 AL C-160531 FG C-160532 PL C-160533 VPO C-160534</p> <p>14x20 AL C-160541 PL C-160543 VPO C-160544</p>	<p><b>CAUTION</b></p> <p>EAR PROTECTION REQUIRED</p> <p>3x5 VPO C-160614 7x10 AL C-160621 FG C-160622 PL C-160623 VPO C-160624</p> <p>10x14 AL C-160631 FG C-160632 PL C-160633 VPO C-160634</p> <p>14x20 AL C-160641 PL C-160643 VPO C-160644</p>	<p><b>CAUTION</b></p> <p>EAR PROTECTION REQUIRED AFTER ___HRS dbA</p> <p>3x5 VPO C-160714 7x10 AL C-160721 FG C-160722 PL C-160723 VPO C-160724</p> <p>10x14 AL C-160731 FG C-160732 PL C-160733 VPO C-160734</p> <p>14x20 AL C-160741 PL C-160743 VPO C-160744</p>	<p><b>CAUTION</b></p> <p>EAR PROTECTION REQUIRED IN THIS AREA</p> <p>3x5 VPO C-160814 7x10 AL C-160821 FG C-160822 PL C-160823 VPO C-160824</p> <p>10x14 AL C-160831 FG C-160832 PL C-160833 VPO C-160834</p> <p>14x20 AL C-160841 PL C-160843 VPO C-160844</p>	<p><b>CAUTION</b></p> <p>EAR PROTECTION REQUIRED NOISE LEVEL IS ABOVE 85dba</p> <p>3x5 VPO C-160914 7x10 AL C-160921 FG C-160922 PL C-160923 VPO C-160924</p> <p>10x14 AL C-160931 FG C-160932 PL C-160933 VPO C-160934</p> <p>14x20 AL C-160941 PL C-160943 VPO C-160944</p>	<p><b>CAUTION</b></p> <p>EAR PROTECTION REQUIRED WHEN THIS EQUIPMENT IS OPERATING</p> <p>3x5 VPO C-161114 7x10 AL C-161121 FG C-161122 PL C-161123 VPO C-161124</p> <p>10x14 AL C-161131 FG C-161132 PL C-161133 VPO C-161134</p> <p>14x20 AL C-161141 PL C-161143 VPO C-161144</p>	<p><b>CAUTION</b></p> <p>ELECTRICAL HAZARD</p> <p>3x5 VPO C-960214 7x10 AL C-960221 FG C-960222 PL C-960223 VPO C-960224</p> <p>10x14 AL C-960231 FG C-960232 PL C-960233 VPO C-960234</p> <p>14x20 AL C-960241 PL C-960243 VPO C-960244</p>
--	--	---	---	---	---	--

<p><b>CAUTION</b></p> <p>ELECTRICAL SHOCK HAZARD</p> <p>3x5 VPO C-161314 7x10 AL C-161321 FG C-161322 PL C-161323 VPO C-161324</p> <p>10x14 AL C-161331 FG C-161332 PL C-161333 VPO C-161334</p> <p>14x20 AL C-161341 PL C-161343 VPO C-161344</p>	<p><b>CAUTION</b></p> <p>EMERGENCY STOP</p> <p>3x5 VPO C-161414 7x10 AL C-161421 FG C-161422 PL C-161423 VPO C-161424</p> <p>10x14 AL C-161431 FG C-161432 PL C-161433 VPO C-161434</p> <p>14x20 AL C-161441 PL C-161443 VPO C-161444</p>	<p><b>CAUTION</b></p> <p>EMERGENCY STOP BUTTON</p> <p>3x5 VPO C-960114 7x10 AL C-960121 FG C-960122 PL C-960123 VPO C-960124</p> <p>10x14 AL C-960131 FG C-960132 PL C-960133 VPO C-960134</p> <p>14x20 AL C-960141 PL C-960143 VPO C-960144</p>	<p><b>CAUTION</b></p> <p>EMPLOYEES ARE NOT PERMITTED TO REMOVE GUARDS OR OPERATE MACHINE WITHOUT THEM</p> <p>3x5 VPO C-161514 7x10 AL C-161521 FG C-161522 PL C-161523 VPO C-161524</p> <p>10x14 AL C-161531 FG C-161532 PL C-161533 VPO C-161534</p> <p>14x20 AL C-161541 PL C-161543 VPO C-161544</p>	<p><b>CAUTION</b></p> <p>ENTRY PROHIBITED WITHOUT PERMIT TEST FOR O2 DEFICIENCY, H2S AND COMBUSTIBLE VAPORS</p> <p>3x5 VPO C-161614 7x10 AL C-161621 FG C-161622 PL C-161623 VPO C-161624</p> <p>10x14 AL C-161631 FG C-161632 PL C-161633 VPO C-161634</p> <p>14x20 AL C-161641 PL C-161643 VPO C-161644</p>	<p><b>CAUTION</b></p> <p>EQUIPMENT MAY MOVE AUTOMATICALLY WITHOUT WARNING</p> <p>3x5 VPO C-161714 7x10 AL C-161721 FG C-161722 PL C-161723 VPO C-161724</p> <p>10x14 AL C-161731 FG C-161732 PL C-161733 VPO C-161734</p> <p>14x20 AL C-161741 PL C-161743 VPO C-161744</p>	<p><b>CAUTION</b></p> <p>EQUIPMENT REMOTELY CONTROLLED</p> <p>3x5 VPO C-161814 7x10 AL C-161821 FG C-161822 PL C-161823 VPO C-161824</p> <p>10x14 AL C-161831 FG C-161832 PL C-161833 VPO C-161834</p> <p>14x20 AL C-161841 PL C-161843 VPO C-161844</p>
--	---	--	---	---	---	--

<p><b>CAUTION</b></p> <p>EQUIPMENT STARTS AUTOMATICALLY</p> <p>3x5 VPO C-161914 7x10 AL C-161921 FG C-161922 PL C-161923 VPO C-161924</p> <p>10x14 AL C-161931 FG C-161932 PL C-161933 VPO C-161934</p> <p>14x20 AL C-161941 PL C-161943 VPO C-161944</p>	<p><b>CAUTION</b></p> <p>EYE PROTECTION AND HARD HATS MUST BE WORN IN THIS AREA</p> <p>3x5 VPO C-162114 7x10 AL C-162121 FG C-162122 PL C-162123 VPO C-162124</p> <p>10x14 AL C-162131 FG C-162132 PL C-162133 VPO C-162134</p> <p>14x20 AL C-162141 PL C-162143 VPO C-162144</p>	<p><b>CAUTION</b></p> <p>EYE PROTECTION AREA</p> <p>3x5 VPO C-162214 7x10 AL C-162221 FG C-162222 PL C-162223 VPO C-162224</p> <p>10x14 AL C-162231 FG C-162232 PL C-162233 VPO C-162234</p> <p>14x20 AL C-162241 PL C-162243 VPO C-162244</p>	<p><b>CAUTION</b></p> <p>EYE PROTECTION AREA CONTACT LENSES NOT ALLOWED</p> <p>3x5 VPO C-162414 7x10 AL C-162421 FG C-162422 PL C-162423 VPO C-162424</p> <p>10x14 AL C-162431 FG C-162432 PL C-162433 VPO C-162434</p> <p>14x20 AL C-162441 PL C-162443 VPO C-162444</p>	<p><b>CAUTION</b></p> <p>EYE PROTECTION MUST BE WORN IN THIS AREA</p> <p>3x5 VPO C-162514 7x10 AL C-162521 FG C-162522 PL C-162523 VPO C-162524</p> <p>10x14 AL C-162531 FG C-162532 PL C-162533 VPO C-162534</p> <p>14x20 AL C-162541 PL C-162543 VPO C-162544</p>	<p><b>CAUTION</b></p> <p>EYE PROTECTION MUST BE WORN WHEN CLEANING THIS EQUIPMENT</p> <p>3x5 VPO C-162614 7x10 AL C-162621 FG C-162622 PL C-162623 VPO C-162624</p> <p>10x14 AL C-162631 FG C-162632 PL C-162633 VPO C-162634</p> <p>14x20 AL C-162641 PL C-162643 VPO C-162644</p>	<p><b>CAUTION</b></p> <p>EYE PROTECTION REQUIRED</p> <p>3x5 VPO C-162714 7x10 AL C-162721 FG C-162722 PL C-162723 VPO C-162724</p> <p>10x14 AL C-162731 FG C-162732 PL C-162733 VPO C-162734</p> <p>14x20 AL C-162741 PL C-162743 VPO C-162744</p>
---	---	--	---	---	---	--

<p><b>CAUTION</b></p> <p>EYE PROTECTION REQUIRED BEYOND THIS POINT</p> <p>3x5 VPO C-162814 7x10 AL C-162821 FG C-162822 PL C-162823 VPO C-162824</p> <p>10x14 AL C-162831 FG C-162832 PL C-162833 VPO C-162834</p> <p>14x20 AL C-162841 PL C-162843 VPO C-162844</p>	<p><b>CAUTION</b></p> <p>EYE PROTECTION REQUIRED IN THIS AREA</p> <p>3x5 VPO C-162914 7x10 AL C-162921 FG C-162922 PL C-162923 VPO C-162924</p> <p>10x14 AL C-162931 FG C-162932 PL C-162933 VPO C-162934</p> <p>14x20 AL C-162941 PL C-162943 VPO C-162944</p>	<p><b>CAUTION</b></p> <p>EYE PROTECTION REQUIRED WHEN EQUIPMENT IS OPERATING</p> <p>3x5 VPO C-171514 7x10 AL C-171521 FG C-171522 PL C-171523 VPO C-171524</p> <p>10x14 AL C-171531 FG C-171532 PL C-171533 VPO C-171534</p> <p>14x20 AL C-171541 PL C-171543 VPO C-171544</p>	<p><b>CAUTION</b></p> <p>EYE PROTECTION REQUIRED WHEN USING COMPRESSED AIR</p> <p>3x5 VPO C-163114 7x10 AL C-163121 FG C-163122 PL C-163123 VPO C-163124</p> <p>10x14 AL C-163131 FG C-163132 PL C-163133 VPO C-163134</p> <p>14x20 AL C-163141 PL C-163143 VPO C-163144</p>	<p><b>CAUTION</b></p> <p>EYE PROTECTION REQUIRED WHILE USING THIS MACHINE</p> <p>3x5 VPO C-163214 7x10 AL C-163221 FG C-163222 PL C-163223 VPO C-163224</p> <p>10x14 AL C-163231 FG C-163232 PL C-163233 VPO C-163234</p> <p>14x20 AL C-163241 PL C-163243 VPO C-163244</p>	<p><b>CAUTION</b></p> <p>EYE PROTECTION, GLOVES, APRONS MUST BE WORN WHEN HANDLING CHEMICALS</p> <p>3x5 VPO C-163314 7x10 AL C-163321 FG C-163322 PL C-163323 VPO C-163324</p> <p>10x14 AL C-163331 FG C-163332 PL C-163333 VPO C-163334</p> <p>14x20 AL C-163341 PL C-163343 VPO C-163344</p>	<p><b>CAUTION</b></p> <p>FACE LADDER WHEN DESCENDING</p> <p>3x5 VPO C-260114 7x10 AL C-260121 FG C-260122 PL C-260123 VPO C-260124</p> <p>10x14 AL C-260131 FG C-260132 PL C-260133 VPO C-260134</p> <p>14x20 AL C-260141 PL C-260143 VPO C-260144</p>
--	---	--	--	---	--	--

# CAUTION

# THE SIGNS OF A SAFE INDUSTRY



**CAUTION**  
FACE MASK  
MUST BE WORN  
IN SPRAY BOOTH

3x5 VPO C-261814  
7x10 AL C-261821  
FG C-261822  
PL C-261823  
VPO C-261824  
10x14 AL C-261831  
FG C-261832  
PL C-261833  
VPO C-261834  
14x20 AL C-261841  
PL C-261843  
VPO C-261844

**CAUTION**  
FACE SHIELD AND  
GLOVES REQUIRED  
WHEN USING  
THIS EQUIPMENT

3x5 VPO C-260314  
7x10 AL C-260321  
FG C-260322  
PL C-260323  
VPO C-260324  
10x14 AL C-260331  
FG C-260332  
PL C-260333  
VPO C-260334  
14x20 AL C-260341  
PL C-260343  
VPO C-260344

**CAUTION**  
FACE SHIELD AND  
GOGGLES  
MUST BE WORN  
IN THIS AREA

3x5 VPO C-260414  
7x10 AL C-260421  
FG C-260422  
PL C-260423  
VPO C-260424  
10x14 AL C-260431  
FG C-260432  
PL C-260433  
VPO C-260434  
14x20 AL C-260441  
PL C-260443  
VPO C-260444

**CAUTION**  
FACE SHIELD AND  
GOGGLES MUST BE  
WORN WHEN USING  
THIS MACHINE

3x5 VPO C-260514  
7x10 AL C-260521  
FG C-260522  
PL C-260523  
VPO C-260524  
10x14 AL C-260531  
FG C-260532  
PL C-260533  
VPO C-260534  
14x20 AL C-260541  
PL C-260543  
VPO C-260544

**CAUTION**  
FACE  
SHIELD  
AREA

3x5 VPO C-260614  
7x10 AL C-260621  
FG C-260622  
PL C-260623  
VPO C-260624  
10x14 AL C-260631  
FG C-260632  
PL C-260633  
VPO C-260634  
14x20 AL C-260641  
PL C-260643  
VPO C-260644

**CAUTION**  
FACE SHIELD APRON  
AND RUBBER GLOVES  
REQUIRED WHEN  
HANDLING BATTERIES  
AND ADDING WATER

3x5 VPO C-260714  
7x10 AL C-260721  
FG C-260722  
PL C-260723  
VPO C-260724  
10x14 AL C-260731  
FG C-260732  
PL C-260733  
VPO C-260734  
14x20 AL C-260741  
PL C-260743  
VPO C-260744

**CAUTION**  
FALL  
PROTECTION  
REQUIRED

3x5 VPO C-981114  
7x10 AL C-981121  
FG C-981122  
PL C-981123  
VPO C-981124  
10x14 AL C-981131  
FG C-981132  
PL C-981133  
VPO C-981134  
14x20 AL C-981141  
PL C-981143  
VPO C-981144

**CAUTION**  
FIRE LANE  
KEEP CLEAR

3x5 VPO C-260914  
7x10 AL C-260921  
FG C-260922  
PL C-260923  
VPO C-260924  
10x14 AL C-260931  
FG C-260932  
PL C-260933  
VPO C-260934  
14x20 AL C-260941  
PL C-260943  
VPO C-260944

**CAUTION**  
FLAMMABLE

3x5 VPO C-960414  
7x10 AL C-960421  
FG C-960422  
PL C-960423  
VPO C-960424  
10x14 AL C-960431  
FG C-960432  
PL C-960433  
VPO C-960434  
14x20 AL C-960441  
PL C-960443  
VPO C-960444

**CAUTION**  
FLAMMABLE  
VAPORS

3x5 VPO C-261114  
7x10 AL C-261121  
FG C-261122  
PL C-261123  
VPO C-261124  
10x14 AL C-261131  
FG C-261132  
PL C-261133  
VPO C-261134  
14x20 AL C-261141  
PL C-261143  
VPO C-261144

**CAUTION**  
FLOOR LOAD  
\_\_\_\_LBS.  
PER SQUARE FOOT

3x5 VPO C-261214  
7x10 AL C-261221  
FG C-261222  
PL C-261223  
VPO C-261224  
10x14 AL C-261231  
FG C-261232  
PL C-261233  
VPO C-261234  
14x20 AL C-261241  
PL C-261243  
VPO C-261244

**CAUTION**  
FOOT PROTECTION  
REQUIRED  
IN THIS AREA

3x5 VPO C-261314  
7x10 AL C-261321  
FG C-261322  
PL C-261323  
VPO C-261324  
10x14 AL C-261331  
FG C-261332  
PL C-261333  
VPO C-261334  
14x20 AL C-261341  
PL C-261343  
VPO C-261344

**CAUTION**  
GLOVES AND  
GOGGLES REQUIRED  
WHEN FILLING TANKS

3x5 VPO C-360114  
7x10 AL C-360121  
FG C-360122  
PL C-360123  
VPO C-360124  
10x14 AL C-360131  
FG C-360132  
PL C-360133  
VPO C-360134  
14x20 AL C-360141  
PL C-360143  
VPO C-360144

**CAUTION**  
GLOVES AND  
GOGGLES POSITIVELY  
MUST BE WORN

3x5 VPO C-960514  
7x10 AL C-960521  
FG C-960522  
PL C-960523  
VPO C-960524  
10x14 AL C-960531  
FG C-960532  
PL C-960533  
VPO C-960534  
14x20 AL C-960541  
PL C-960543  
VPO C-960544

**CAUTION**  
GOGGLES  
POSITIVELY  
MUST BE WORN

3x5 VPO C-360214  
7x10 AL C-360221  
FG C-360222  
PL C-360223  
VPO C-360224  
10x14 AL C-360231  
FG C-360232  
PL C-360233  
VPO C-360234  
14x20 AL C-360241  
PL C-360243  
VPO C-360244

**CAUTION**  
GOGGLES POSITIVELY  
MUST BE WORN  
WHEN OPERATING  
THIS MACHINE

3x5 VPO C-360414  
7x10 AL C-360421  
FG C-360422  
PL C-360423  
VPO C-360424  
10x14 AL C-360431  
FG C-360432  
PL C-360433  
VPO C-360434  
14x20 AL C-360441  
PL C-360443  
VPO C-360444

**CAUTION**  
GROUND ALL  
BARRELS

3x5 VPO C-360514  
7x10 AL C-360521  
FG C-360522  
PL C-360523  
VPO C-360524  
10x14 AL C-360531  
FG C-360532  
PL C-360533  
VPO C-360534  
14x20 AL C-360541  
PL C-360543  
VPO C-360544

**CAUTION**  
GROUND  
BARRELS  
BEFORE USING

3x5 VPO C-360614  
7x10 AL C-360621  
FG C-360622  
PL C-360623  
VPO C-360624  
10x14 AL C-360631  
FG C-360632  
PL C-360633  
VPO C-360634  
14x20 AL C-360641  
PL C-360643  
VPO C-360644

**CAUTION**  
H<sub>2</sub>S  
MAY BE PRESENT  
DO NOT ENTER THIS AREA  
WITHOUT APPROVED H<sub>2</sub>S  
DETECTION EQUIPMENT

3x5 VPO C-370114  
7x10 AL C-370121  
FG C-370122  
PL C-370123  
VPO C-370124  
10x14 AL C-370131  
FG C-370132  
PL C-370133  
VPO C-370134  
14x20 AL C-370141  
PL C-370143  
VPO C-370144

**CAUTION**  
H<sub>2</sub>S  
POISONOUS GAS  
MAY BE PRESENT

3x5 VPO C-370214  
7x10 AL C-370221  
FG C-370222  
PL C-370223  
VPO C-370224  
10x14 AL C-370231  
FG C-370232  
PL C-370233  
VPO C-370234  
14x20 AL C-370241  
PL C-370243  
VPO C-370244

**CAUTION**  
HARD HAT  
AREA

3x5 VPO C-370314  
7x10 AL C-370321  
FG C-370322  
PL C-370323  
VPO C-370324  
10x14 AL C-370331  
FG C-370332  
PL C-370333  
VPO C-370334  
14x20 AL C-370341  
PL C-370343  
VPO C-370344

**CAUTION**  
HARD HAT  
REQUIRED

3x5 VPO C-960314  
7x10 AL C-960321  
FG C-960322  
PL C-960323  
VPO C-960324  
10x14 AL C-960331  
FG C-960332  
PL C-960333  
VPO C-960334  
14x20 AL C-960341  
PL C-960343  
VPO C-960344

**CAUTION**  
HARD HATS AND  
EYE PROTECTION  
MUST BE WORN  
IN THIS AREA

3x5 VPO C-370514  
7x10 AL C-370521  
FG C-370522  
PL C-370523  
VPO C-370524  
10x14 AL C-370531  
FG C-370532  
PL C-370533  
VPO C-370534  
14x20 AL C-370541  
PL C-370543  
VPO C-370544

**CAUTION**  
HARD HATS AND  
EYE PROTECTION  
REQUIRED

3x5 VPO C-370614  
7x10 AL C-370621  
FG C-370622  
PL C-370623  
VPO C-370624  
10x14 AL C-370631  
FG C-370632  
PL C-370633  
VPO C-370634  
14x20 AL C-370641  
PL C-370643  
VPO C-370644

**CAUTION**  
HARD HATS  
MUST BE WORN  
IN THIS AREA

3x5 VPO C-370714  
7x10 AL C-370721  
FG C-370722  
PL C-370723  
VPO C-370724  
10x14 AL C-370731  
FG C-370732  
PL C-370733  
VPO C-370734  
14x20 AL C-370741  
PL C-370743  
VPO C-370744

**CAUTION**  
HARD HATS  
REQUIRED

3x5 VPO C-370814  
7x10 AL C-370821  
FG C-370822  
PL C-370823  
VPO C-370824  
10x14 AL C-370831  
FG C-370832  
PL C-370833  
VPO C-370834  
14x20 AL C-370841  
PL C-370843  
VPO C-370844

**CAUTION**  
HARD HATS  
REQUIRED  
IN THIS AREA

3x5 VPO C-960614  
7x10 AL C-960621  
FG C-960622  
PL C-960623  
VPO C-960624  
10x14 AL C-960631  
FG C-960632  
PL C-960633  
VPO C-960634  
14x20 AL C-960641  
PL C-960643  
VPO C-960644

**CAUTION**  
HARD HATS,  
EYE PROTECTION,  
EAR PROTECTION  
MUST BE WORN  
BEYOND THIS POINT

3x5 VPO C-371014  
7x10 AL C-371021  
FG C-371022  
PL C-371023  
VPO C-371024  
10x14 AL C-371031  
FG C-371032  
PL C-371033  
VPO C-371034  
14x20 AL C-371041  
PL C-371043  
VPO C-371044